



Notice to Mariners
Maritime Safety Information

Client Name/contact details:

Alexandra Thomson
OrcaDes Marine Management Consultants Ltd.
+44 (0) 1856 874884
info@orcademarine.co.uk

Details of Hazard:

A 4-anchor mooring spread will be installed in Scapa Flow, SE of Anchorage No. 4, the installation will take place on the 25th May 2020.

The mooring arrangement consists of 4 HHP anchors, the NW and SW anchors both connect into a 100m chain which both join into the same shackle, connecting a 37m riser wire leading to a buoy. The NE and SE anchors and chain have the same configuration.

The vessel that will be used for installation is the C-Odyssey.

Positions:

Component	Lat and Long	UTM WGS84 (Zone 30)
NW HHP Anchor	58 52.34'N 002 56.77'W	503102e 6525833n
NE HHP Anchor	58 52.34'N 002 56.32' W	503528e 6525833n
SE HHP Anchor	58 52.26'N 002 56.32'W	503528e 6525691n
SW HHP Anchor	58 52.26'N 002 56.70'W	503102e 6525692n
W Joining Shackle	58 52.30'N 002 56.70'W	503172e 6525763n
E Joining Shackle	58 52.30'N 002 56.40'W	503456e 6525763n
W Buoy	58 52.30'N 002 56.70'W	503201e 6525763n
E Buoy	58 52.30'N 002 56.44'W	503426e 6525763n

Details of lights, buoys and other navigational aids:

The buoys will be yellow can buoys which have a yellow flashing light 1 FY 5s. Light range 1nm.

Instructions to vessels:

Vessels should maintain a continual listening watch on channels 11 and 16. Mariners are requested to give the area a wide berth.

Name and Signature
Alexandra Thomson

Date
21/05/2020